The resistors are crucial to getting accurate readings from the sensors. do NOT forget them.

The two 4-digit displays are completely optional and only add readability

Connect CLK and D0 on your four digit display to any digital pin. Vcc to 5v and gnd to gnd

