BUTTER WARMER TEMPERATURE CONTROLLER
SCHEMATIC DIAGRAM



Resistors R11* & R12*, wirewound:
120V, 2x 2k2, 10W
OR
240V, 2x 8k2, 10W

Fuse F1*:
120V, 250mA
OR
240V, 100mA

Transformer Tr1*:
120V primary, 15V secondary, 3VA
OR
240V primary, 15V secondary, 3VA

All resistors 1/4W, 5% except R11 & R12