SolidWorks: Decals

In This Instructable:

1. How to place Decals on Faces of Existing Parts or Assemblies
2. How to Create Decals with Free Online Label Maker

Basic Steps for Decal Placement:

- Create Part or Assembly
- Go to Appearance tab in Feature Tree Window
- Right-Click in bottom of Window
- Browse for saved decal or select SolidWorks provided decal
- Select Face you want to add Decal and press OK
- Adjust location, size, and angle of decal on selected face