Procedure to setup the XBee modules using X-CTU software.

Step1:
Check With the Device manager the COM port number assigned to the Serial/USB converter.
Here COM4.

Step2:
Launch XCTU software. Click on the **Discover Radio Modules...** button at the top left.
Select the COM port to scan (COM4). And click **Finish**.

Step3:
Set or verify the default communication parameters for the Serial Communication and click **Finish**.

Step4:
The XBee module should appears in the left window.
Select it and click on **Add selected devices** button.

Step5:

You can let most of the default parameters.

For a simple serial communication between the 2 modules you can just configure the following settings:

	XBee 1	XBee2
PAN ID	1111	1111
DL	1	2
MY	2	1

Step6:

Do not forget to save the configuration in the module by clciking the **Write** icon.

This configuration step need to be done only once.