



Config: M2 M1 M0

Full step	0	0	0
1/2	0	0	1
1/4	0	1	0
1/8	0	1	1
1/16	1	0	0
1/32	1	0	1
1/64	1	1	0
1/128	1	1	1

PWM Timers:
 X_STEP PB8 TIM4 CH3
 Y_STEP PA15 TIM2 CH1
 Z_STEP PC9 TIM8 CH4
 EX_STEP PB4 TIM3 CH1

