

The problem: DTV convertor stops working (APEX)

The reason: 1 bad capacitor on power supply board.



The solution: replace with higher voltage rating caps.