



Fisr frame needs holes in the inner sides to fix the threaded rod

First Frame: Don't drill all the way through!!  
Last Frame: Drill big enough to fit the countersunk nut (13mm)

Dept.	Technical reference	Created by <b>Kai Laufer</b>	Approved by <b>27.06.2021</b>	Document status
		Document type	DWG No.	File
		<b>Bench_2</b>		
Rev.	Date of issue	Sheet		
1/1		1/1		

Aluminum Parts