


Idle

Choosing Power A Supply

> If You Only Have Whole Devices

Use an "BO Plus" Certified Power Supply

	80 PLUS [®]	BRONZE	BO PLUS [®] SILVER	BO PLUS [®] GOLD	BO PLUS [®] PLATINUM	BO PLUS TITANIUM
at 10% load						90%
at 20% load	80%	82%	85%	87%	90%	92%
at 50% load	80%	85%	88%	90%	92%	94%
at 100% load	80%	82%	85%	87%	89%	90%



If You Only Have Standard Components

If You Can Buy Special Components





