




You will need to make a total of 8 of these cranks



Note: these two cranks should be about 80 degrees out of phase, which can be adjusted by loosening the beams holding the gear train and rotating one gear independently

The cranks can be repositioned by loosening the gear train's beams, and rotating one of the 40 tooth gears a couple of teeth

