


To accommodate the unevenness of the slab grooves were routed deeper, so legs are longer.



Tees may not be in the same orientation as constructed