

All ↑ measurements are to INSIDE OF TOP RAIL using TipTop Z-Rails. Not guaranteed for all manufacturers-adjust if you need to.

All ← measurements are to left edge of panel.

Red (rail mounting) measurements are to left edge of panel and top or bottom edge of panel. You may want to do all four corners but you need to measure out the correct hp spacing for your rack if using Z-rails instead of slide nuts. Also you may want to double the mounting holes to the inside and bridge them to give yourself some slide room.