

cables from
the slip rings

M3 nut used
as spacer

4x M3 L-shaped
supports at 90°

Alu C-shaped
revolving arm

4x plexiglas
loops for the
hub

plexiglas rings

3x M4 screw
with nuts at 120°

Drilled Hole for
the cables

cables to
the connector

Filed or
milled notch
for the cables

Fixed central
screw for the
flange

