

FULL FUNCTION CONTROLLER



PICAXE-08M		PIN OUTS	
+V	1	8	0V
Serial In	2	7	Out 0 / Serial Out / Infraout
ADC 4 / Out 4 / In 4	3	6	In 1 / Out 1 / ADC 1
Infrain / In 3	4	5	In 2 / Out 2 / ADC 2 / pwm 2 / tune

DC POWER JACK

