


Lion circuits DFM

DFM Summary

InstaDFM checks are updated below. Please review.

If you believe your design was flagged by mistake, you can ask for a manual review.




Top Copper Trace Width



Checks Passed

Description

All trace widths on top copper are > 8 mil




Top Copper Minimum Spacing Between Traces



Checks Passed

Description

Spacing between adjacent traces are > 8 mil




Bottom Copper Trace Width



Checks Passed

Description

All trace width on bottom copper are > 8 mil




Bottom Copper Minimum Spacing Between Traces



Checks Passed

Description

Spacing between adjacent traces are > 8 mil




Top Silk-Solder Overlap



Checks Passed

Description

No overlap between silk screen and solder pad detected.




Top Silk Trace Width



Checks Passed

Description

All silk screen text widths are > 6 mil




Bottom Silk-Solder Overlap



Checks Passed

Description

No overlap between silk screen and solder pad detected.




Bottom Silk Trace Width



Checks Passed

Description

All silk screen text widths are > 6 mil



Drill Errors



Checks Passed

Description

No drill errors found