

FIT FOUR PUSH BUTTONS AND SOLDER







POWER MODULE
FIT PINS FIRST AND
SOLDER. MOUNT
MODULE ON PINS
AND SOLDER.
DON'T ADJUST AND
ENSURE POWER IN
IS FACING THE
CENTRE OF PCB

FIT CAPACITOR 25MFD 25V OBSERVE POLARITY

SOUNDER
MAKES SURE THE A
+ IS FACING DOWN





IF YOU ARE USING HOLDERS FOR NANO AND CLOCK CUT THE STRIP AND NOTE PINS 3-13-14 HAVE BEEN REMOVED

THE CLOCK MODULE REQUIRES A 5 PIN STRIP TO BE SOLDERED IN.
AFTER SOLDERING REMOVE THE PLASTIC STRIP.



MOUNT CLOCK WITH SUPPLIED BRACKET USING SUPPLIED NUT AND BOLT



